



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining


MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

May 20, 2010

Reviewed: 

<b>Mine Name:</b> Dove Creek Quarry	<b>Permit Number:</b> M/003/0016
<b>Operator Name:</b> Dove Creek Quarries, Inc.	<b>Inspection Date:</b> October 6, 2010
<b>Inspector(s):</b> Lynn Kunzler	<b>Time:</b> 2:00 pm
<b>Other Participants:</b> Dave Morris, Operator	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Routine inspection while in area.

#### Inspection Summary:

The annual permit fee had not been remitted at the time of this inspection. Mr. Morris was under the impression that Mr. Cates had remitted the payment. He will check into this and if fees were not paid he will send in payment himself (fees were received October 26<sup>th</sup>). This site was inactive during this inspection. Activity has been limited to the Cliff Quarry (and expansion area) and the Main Quarry. Quarry pits are deeper, but the overall footprint has not changed significantly since the last inspection. The operator has posted signs to warn public of mine-related hazards. There were no signs of accelerated erosion. Garbage is being properly disposed of.

Photos were taken to document site conditions. Photos in file.

#### Conclusions and Recommendations:

No non-compliance issues were observed. Continue to monitor this site when in the area.

Inspector's Signature



O:\M003-BoxElder\M0030016-DoveCreek\inspections\Insp-1062009.doc